

**BCM 3309**

**1999 - 2010 Multiple Vehicles**

**Flutter/ Turbulence Noise At Highway Speeds With Rear Windows Or Moon/ Sun Roof Open**

Some 1999 - 2010 vehicles may exhibit a flutter/ turbulence noise (helicopter noise) at highway speeds when the rear door window's or sun/ moon roof are open. This condition is a characteristic of the vehicles body design and is also a characteristic of competitive vehicles with a similar body style. This condition can be reduced by lowering either one, or both, of the front windows at least 2 inches - no service action is recommended for this condition.