

**TSB 10-05-10**

**2009 Escape/ Mariner, 2010 Fusion/ Milan - 6F35 Transmission**

**Fluid Leak - Seal - Left Side Half Shaft**

This article supersedes TSB 10-01-05 to update the part list. Some 2009 Escape, Mariner, 2010 Fusion and Milan vehicles equipped with a 6F35 automatic transmission may experience a fluid leak coming from the left side half shaft seal. This may be due to seal and/ or bushing wear caused by the half shaft surface finish. Refer to TSB 10-05-10 and follow the service procedure to repair leaks at the left side half shaft seal.