

BCM 3317 - Appearance Of Gray Or Milky Axle Lubricant

Some 2004 - 2011 F-Super Duty, 2004 - 2010 E-Series, F-150, Mustang, Crown Vic/ Grand Marquis, Town Car, Expedition/ Navigator, Explorer/ Mountaineer, and Explorer Sport Trac vehicles equipped with Ford/ Sterling front and/ or rear axles may exhibit axle lubricant that appears milky or gray. The appearance is most likely discoloration caused by marking compound used at the factory to check gear tooth patterns. This condition may be more apparent on independent rear and/ or front suspension axles as there is less lubricant volume present. This condition has no effect on the performance or durability of the axle and is considered normal. Do not change the lubricant for this condition